

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED

DEC 27 1993

DIVISION OF
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-93 To (mo./yr.) 1-94
 2. DOGM File Number (Mine No): M/0231022
 3. Mine Name: Topaz Valley Limestone
 4. Mineral(s) Mined (or permitted to mine): Crushed Limestone
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
1/4, SW 1/4, Section 21, Township 13S, Range 11W
1/4, SE 1/4, Section 21, Township 13S, Range 11W
1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: Rancho Equipment Services
 8. Permanent Street Address: 279 East Main
City, State, Zip: Delta, Utah 84624
Phone: 801-864-3971
 9. Company Representative (or designated operator):
Name: Robert B. Thomas
Title: Vice-President - General Manager
Business Address: 279 East Main - P.O. Box 591
City, State, Zip: Delta, Utah 84624
Phone: 801-864-3971 Home 864-4444
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 68,000 Tons,

3. How much **additional acreage** was disturbed during the past year? none
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
No new surface disturbances.
5. How much acreage was **reclaimed** during the past year? none
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
Complete area is presently being used; as mine grows other area can begin to be reclaimed.
7. What is the **total disturbed acreage** at years end? 5 Acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Plans Remain about the same. Quarry will grow a little more but we are about to get our large Mining permit approved in near future.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Robert B. Thomas

Title of Operator:

Vice - President

Signature of Operator:

Robert B. Thomas

Date:

Dec. 16, 1993